7570-7167-7208-2034

TEST REPORT

1. NO : CT21-120622E
2. Client
   - ○ Name : SEOHAN ANTAMIN
   - ○ Address : 51st 622 Angogae-ro, Namdong-gu, Incheon
3. Date of Test : 2021.11.16 ~ 2022.09.08
4. Use of Report : The report for Quality Management
5. Test Sample : A0P-8827
6. Test Method
   (1) KS F 2274:2018, KS A 0063:2015

Affirmation	Tested By Name : Jong Hyuk Park	Technical Manager Name : LEE Hoo Seok


This report is related with KOLAS and KS Q ISO/IEC 17025.
Our report apply only to the standards or procedures identified and to the sample(s) tested unless otherwise specified. The test results are not indicative of representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products. The results of using only a portion of this report cannot be guaranteed. The authenticity of this test report can be checked on KCL website(www.kcl.re.kr).

The above test report provides test result(s) under the scope accredited by Korea Laboratory Accreditation Scheme (KOLAS), which signed the ILAC-MRA.

2022.09.08

Korea Conformity Laboratories President Jo, Yung Tae

Accredited by KOLAS, Republic of KOREA





TEST REPORT

No : CT21-120622E

7. Test Results

1) A0P-8827

Test Item(s)	Unit	Test Method	Test Results	Remark	Loc.
Accelerated Weathering Test(Xenon, 1 000 hours)-Color Difference(ΔE^*_{ab})	-	(1)	0.3	(23 ± 2) ℃, (55 ± 10) % R.H.	A
Accelerated Weathering Test(Xenon, 2 000 hours)-Color Difference(ΔE^*_{ab})	-	(1)	0.4		
Accelerated Weathering Test(Xenon, 3 000 hours)-Color Difference(ΔE^*_{ab})	-	(1)	0.6		
Accelerated Weathering Test(Xenon, 4 000 hours)-Color Difference(ΔE^*_{ab})	-	(1)	0.7		
Accelerated Weathering Test(Xenon, 5 000 hours)-Color Difference(ΔE^*_{ab})	-	(1)	0.9		

※ Accelerated Weathering Test Condition
- Inner Filter : S.Borosilicate, Outer Filter : S.Borosilicate
- Black Pannel Temperature : (63 ± 3) ℃
- Relative Humidity : (50 ± 5) %
- Test Cycle : 18 min irradiance and Water Spray after 102 min irradiance
- Irradiance : 550 W/m² @ (300 - 800) nm

※ Location

A : 595-10, Pyeongsin 1-ro, Daesan-eup, Seosan-si, Chungnam, 31900, Korea

----- End of Report -----

COPY 복사본 KCL COPY 복사본 COPY 복사본